


Building Use Certificate

The Base Stone Public school building near to the Gate has been inspected on Dt.23-07-2020 and structure seems safe and usable in Normal Condition. The school management should have arrangements for the natural calamities i.e. Sudden failure of stone patties, Earthquake, fire, flood, etc.



To.
Base Stone Public School,
At & Post- Ghodasar,
Ta - Mahemdabad
Dist-kheda-387 110.


Deputy Executive Engineer
R. & B. Sub-Division,
Kheda.